




Pressure Loss Chart

Tested by Danish Technological Institute



- Ⓐ: No joint
- Ⓑ: 1 joint
- Ⓒ: 2 joints